

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 12052

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080172-3

RECEIVED FROM

Plant #9

DATE REC'D. 5-2-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.
	322	000000	92	0	23					
10	732732-1 E. Cover Assy Access Fan IPS #1367						QUANTITY			REMARKS
							ACCEPTED	REJECTED		
							10			No. 1367

RECEIVED
BY HMC-1089

INSPECTED
BY

DATE 5-2-57

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST. PASADENA, CALIF.

No. 12053

RECEIVED FROM

Plant #9

DATE REC'D. 5-2-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.
	322	000000	92	0	23					
10	732732-2 D. Cover Assy Access Fan IPS #1028						QUANTITY			REMARKS
							ACCEPTED	REJECTED		
							10			No. 1028

RECEIVED
BY HMC-1259

INSPECTED
BY

DATE 5-2-57

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080172-3